

**TO BE FILLED BY THE INSPECTING OFFICER**

(ASSISTANT ENGINEER)

No: PW1-3838/22/AE/LSGD/VMC

Name of School: The Warwin School, Vaikom

1. Name of Officer : JAYAKUMAR. B  
2. Location : KADUTHURUTHY, VAIKOM  
3. Period for which the Certificate is issued : 2022-23 (Up to 31/03/2023)  
4. Types of Building : Permanent Multi Storeyed RCC Building  
1) 1 X 78.48m x (23.37m+15.17m)/2 (G.F)-  
(14 Class room, 3 Lab, Office, Toilets, Porch, Other rooms)  
3) 1 X 78.48m x (23.37m+15.17m)/2 (F.F)-  
(17 Class room, Office, Toilets, Balcony, Open area/Verandah)  
4) 1 X 78.48m x (23.37m+15.17m)/2 (S.F)-  
(17 Class room, Office, Toilets, Balcony, Open area/Verandah)

5. Nature of defect if any;

- a) Foundation and Basement :  
b) Super structure :  
c) Doors and Windows :  
d) Wood work wrought and put up : Nil  
e) Roof :  
f) Flooring :  
g) Miscellaneous (Cracks if any) :

6. Any major defects noticed which will render the building unsafe in any order : No

7. Whether maintenance work have been done properly : Yes

8. Whether the structure is sound or not for conducting classes : Yes, Sound for conducting classes under normal wind and weather conditions (Trees or branches of trees near the school should be removed before starting the school)

**Note:** 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc

2. Any additional observation deemed necessary for the certificate, may be furnished separately with the Certificate

Certified that the School was inspected by me on 27/05/2022 and found to be, fit to conduct classes for the period for the reasons stated above.

Place: Vaikom

Date : 27/05/2022



Signature :

Designature :

**Municipal Engineer  
Vaikom Municipality**